

1. HOT DIP GALV. 2. SHIPPED UNASSEMBLED. DEVIATION IS RELATED TO LOAD, SOIL
CONDITIONS AND ELEVATION ABOVE GRADE, AND
SHOULD BE DISCUSSED WITH CHANCE APPLICATION
ENGINEERS ON A PROJECT SPECIFIC BASIS.

| LATEST EC NO: |          |      |                    | DATE     | СНАМ | IGED BY | RESP ENGINEER |   |
|---------------|----------|------|--------------------|----------|------|---------|---------------|---|
| EC02819       |          |      | REV.               | 07-23-01 |      | RTIN    | WEST          |   |
|               |          |      |                    |          |      |         |               |   |
|               |          |      |                    |          |      |         |               |   |
|               |          |      |                    |          |      |         |               |   |
|               |          |      |                    |          |      |         |               |   |
| MARTIN        | 07-23-01 | TRIF | TRIPOD SUBASSEMBLY |          |      |         |               |   |
|               |          |      |                    |          |      | SA′     | 107-019203    | , |